

Wildfire Hardened and Energy Efficient Building Assemblies –

Presented by:

Chad Gretzner - Research Engineer & NFPA RWRPP



-

Funded by Energy Codes and Standards Southern California Edison 2025

Mr. Charles J. Kim, P.E.

Sr. Engineer

Southern California Edison

Energy Codes and Standards

4777 N. Irwindale Ave., Irwindale, CA 91706

T. 626-302-0796 **Charles.Kim@sce.com**





Learning Objectives

- 1. Burn Test Study (K&A Building Science & SCE)
- 2. Wildfire Hardened Displays SCE Energy Education Center
- 3. Key Points



Learning Objective #1
Burn Test Study







San Bernardino Regional Emergency Training Center Burn Test January 30th, 2024

The Goal of our Burn Test Study

- To test ignition resistant & noncombustible building materials as an advanced framed assembly, in a high-density setting, to stand alone & survive the full duration of a residential fire.
- Structures facing each other, not side by side.



U-Stucco being installed.



Residential Fires

- The average duration = 60 minutes
 - 15 minutes up to 3 hours
- The average temperature = 1,600° F
 - Extreme fuels and winds = 2,000° F



Burn Structure -

- Needs to last 60 minutes
- Produce direct flame & radiant heat exposures of 1,600° F




Burn Structure -

- Conventionally framed 2"x6"x16" o/c
- Open eave
- Vented attic
- Wood siding
- Insulated, drywalled and taped
- No defensible space
- Combustibles in the 0'-5' zone around the structure

A lot of wood furniture!







Hardened Structure -

- Advanced framing 2" x 6" x 24" O.C. (Less fuel)
- Enclosed eave
- Unvented attic
- Non-combustible siding
- Insulated, drywall and taped
- 60-minute fire rated window
- 60-minute fire rated door
- Defensible space Zone 0 (0'-5')
- SSD 10' from neighboring parcel

Non-Combustible Exterior Siding & Roofing

Lathing



U-stucco (R-2): Single Coat (7/8"-1")
Standard Stucco R-0.20



FR-Clear Coating or Paint: Red Taped Sections



Burn Structure Timeline



4 min. Burn Structure Ignites

Fire-fighters ignited the mulch, vegetation & the pile of firewood around the burn structure with a propane torch.



30 min. Window & Siding Failed

The window frame ignited and failed before the panes of glass failed.

To be noted, the portion of wood siding that was painted with fire-resistant paint lasted for an additional 15 minutes.



60 min. Burn Structure Collapsed

The burn structure collapsed towards the hardened structure due to uneven terrain.

A steel fence or block wall would have helped prevent unnecessary exposure.

Test complete.

The vinyl fence warped and then melted to the ground. It did not ignite.



15 min. Vinyl Fence Melts

This provided additional airflow to the fuels located inside the burn structure.


Temperatures reached 1,600 degrees F and flame lengths up to 12'.



45 min. Door Failed

Video: Kliewer and Associates performs Burn Test for SCE

https://youtu.be/VJKS_qSk9P4?si=eJ2hNJUi3e8pp1jU




Vinyl fence melts and does not sustain flame.



FR-Paint & Coating

FR-paint provided 15 minutes of protection.

Neither are approved in California building codes.





We Did Not Anticipate

- The burn structure collapsing towards the hardened structure.
- Building materials may have to withstand impact.
- · Steel fence or a concrete block wall.
- Wildfire events may have extremely high winds and debris that may fall onto or against your structures.



Design met the anticipated exposure

- Advanced framing 2" x 6" x 24" 0.C. (Less fuel)
- Enclosed eave
- Unvented attic
- Ignition resistant and non-combustible siding
- · Insulated, drywall and taped
- 60-minute fire rated window
- 60-minute fire rated door
- Defensible space
- SSD 10' from neighboring parcel

Forensic Study

1/8" Layer on the 60min. FR-Door Contributes to Direct-Flame Exposure to the Closed Eave.



Observations

- Eaves trap heat.
- Extremely vulnerable to ignition.
- Relatively easy to enclose with non-combustible materials.





Recommendations

- If attics are vented, use ember and fire-rated vents with 1/16"-1/8" openings. Options may include:
 - Stainless steel wire (looks like steel wool).
 - Intumescent firestop materials; Expands when heated which closes the screened openings preventing ember and direct flame exposure.
 - Replaceable cartridge design.
 - Metal louvers over the screen mesh prevents the screen mesh being painted over.

60-Minute Fire Rated Door

1/8-inch layer burned off.



Non-Combustible Core



Heat Transfer at the Hinges

Concentrated heat at the door hinges.

Critical Information



Fiber cement & drywall withstood heat transfer.




Wood stud was scorched at steel hinge.



Recommendations

- Ensure the steel door frame is installed over noncombustible materials such as drywall or fiber cement board.
- Use thermal breaks to prevent heat transfer.
- Caulk any gaps with fire rated caulking or intumescent materials in through-hole penetrations.



Door Recommendations

- 60–120-minute fire-rated door.
 - Highest rating possible when fuel or structure exposures are less than 30' (High-density).
- Must include the equivalent rated door jamb & weather stripping.
 - If steel, install 1/4" fiber cement board between the steel door jamb and wood framing.



Non-Combustible Siding/Roof: U-Stucco

No damage to wood sheathing or underlayment



Heat did not transfer through U-Stucco



SAFTIFIRST 60min. Fire Rated Window

Superlite II-XL



Intumescent Interlayer Expands



SAFTIFIRST 60min. Fire Rated Window

Appears the gypsum pack plastic coating heated up enough to stick to the steel tubing



Wood framing undamaged



Conclusion — Hardening and Defensible Space Provides:

- Additional time for residents to escape
- More time for first responders to arrive
- A safer working environment for first responders to defend the structure
- Evidence that structures can be designed to stand-alone against wildfires

Recent 2025 Palisades Fire



Chasen Architect – Greg Chasen AIA

Learning Objective 2:

Southern California Edison Energy Education Center Wildfire Hardened Module Pullouts



6090 Irwindale Ave, Irwindale, CA 91702 800-336-2822







Roof Framing Factor 6.8% Roof Assembly U-Value 0.026 (2025 Code Attic Space 0.043, Unvented Attic 0.075)


Roof Assembly R-Value 38 (2025 Code R-22, Cathedral Ceilings) R-38)





Wall Framing Factor 17% Wall Assembly U-Value 0.044 (2025 Code 2"x6" 0.069)

Wall Assembly R-Value 25.9 (2025 Code 2"x6" R-21)











Roof Framing Factor 6.8% Roof Assembly U-Value 0.020 (2025 Code Attic Space 0.043, Unvented Attic 0.075)

Roof Assembly R-Value 49.9 (2025 Code R-22, Cathedral Ceilings






Wall Framing Factor 17% Wall Assembly U-Value 0.035 (2025 Code 2"x6" 0.069) Wall Assembly R-Value 25.9 (2025 Code 2"x6" R-21)







Key Points

- Successful hardening against embers, direct flame, radiant heat and convection includes:
 - · Defensible space
 - Non-combustible materials for high-density settings <30'
 - 1hr minimum ignition-resistant materials >30'
 - Prevent thermal bridging:
 - Metal contacting wood framing
 - Advanced framing (less lumber)
 - Enclosing the eaves as they trap heat (w/non-combustible materials)
 - Sealing gaps

Key Points

- Energy Efficiency gains are realized from:
 - Air sealing
 - Proper sealing around fire-rated doors and windows
 - Advanced framing
 - Non-combustible or ignition-resistant thermal barriers added to:
 - Roof decks
 - · Exterior sheathing/siding



